


page 1 of 5

ANNEX A TEST SETUP PHOTOS



140269_1.JPG: Test setup fully anechoic chamber


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F140269E1

 Date of issue:
 10 June 2014
 Order No.:
 14-110269



page 2 of 5

ANNEX A TEST SETUP PHOTOS



140269_2.JPG: Test setup fully anechoic chamber


Test Report No.: F140269E1 Order No.: 14-110269

Examiner: Manuel BASTERT Date of issue: 10 June 2014



page 3 of 5

ANNEX A TEST SETUP PHOTOS



140269_3.JPG: Test setup fully anechoic chamber


Test Report No.: F140269E1 Order No.: F140269

Examiner: Manuel BASTERT Date of issue: 10 June 2014



page 4 of 5

ANNEX A TEST SETUP PHOTOS



140269_4.JPG: Test setup fully anechoic chamber

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F140269E1

 Date of issue:
 10 June 2014
 Order No.:
 14-110269



page 5 of 5

ANNEX A TEST SETUP PHOTOS



140269_5.JPG: Test setup open area test site

Test Report No.: F140269E1 Order No.: F140269

Examiner: Manuel BASTERT Date of issue: 10 June 2014