


page 1 of 5

ANNEX A TEST SETUP PHOTOS



123441_1.JPG: Test setup fully anechoic chamber


Test Report No.: F123441E1 Order No.: 12-113441

Examiner: Manuel BASTERT Date of issue: 18 October 2012



page 2 of 5

ANNEX A TEST SETUP PHOTOS



123441_2.JPG: Test setup fully anechoic chamber


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F123441E1

 Date of issue:
 18 October 2012
 Order No.:
 12-113441



page 3 of 5

ANNEX A TEST SETUP PHOTOS



123441_6.JPG: Test setup fully anechoic chamber


Test Report No.: F123441E1 Order No.: 12-113441

Examiner: Manuel BASTERT Date of issue: 18 October 2012



page 4 of 5

ANNEX A TEST SETUP PHOTOS



123441_7.JPG: Test setup fully anechoic chamber


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F123441E1

 Date of issue:
 18 October 2012
 Order No.:
 12-113441



page 5 of 5

ANNEX A TEST SETUP PHOTOS



123441_8.JPG: Test setup open area test site

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F123441E1

 Date of issue:
 18 October 2012
 Order No.:
 12-113441