Rhein Tech Laboratories, Inc. 360 Herndon Parkway Suite 1400 Herndon, VA 20170 http://www.rheintech.com

Model: 34071 Standards: FCC 15.231/IC RSS-210 ID's: TXL34071/6335A-34071

Report #: 2012203

Client: STI, Inc.

## Appendix A: Change Description

Please refer to the following page.

2306 Airport Road Waterford, Michigan Tel: (248) 673-9898 Fax: (248) 673-1246

48327-1209



American TCB 6731 Whittier Ave. McLean, VA 22101

RE:

FCC ID: TXL34071

IC:

6335A-34071

FCC Permissive change statement

Attn:

**Director of Certification** 

The following changes have been made to this product:

R5 was 47k changed do not stuff.

R3 was 47k changed to 100k.

R1 was 220 ohm changed to 330 ohm.

R4 was 470 ohm changed to do not stuff.

C14 was 4.7pF changed to 2.2pF.

| Dated this    | 3 <sup>rd</sup> day of October, 2012                    |
|---------------|---|
| ву:           | (Signature)   |
| Title:        | ). P.   |
| On behalf of: | Safety Technology International, Inc.<br>(Company Name) |
| Telephone:    | 248-673-9898  |