December 17, 2013

RE: ATCB014862 - Original Equipment & Single Certification Applications - Model: 40914

FCC ID: TYD-CS40914 & IC: 8471A-CS40914 for LogicMark, LLC

I have a few comments on this Application. Please <u>do not put confidential information</u> in your responses to these questions because the response letter will not be held confidential by the FCC. Depending on your answers there may be more questions.

6. Internal photos appear to be missing an RF shield over components on the main board. The schematic diagram shows an RF shield on page 2. Please address this discrepancy.

Response: The schematic shows the shield cans as being non-populated. They are included in the design for possible EU certification.