

Date: August 16, 2010

Telefication B.V. Attn:Dept. FCC TCB Edisonstraat 12a 6902 PK Zevenaar The Netherlands

RFID Function Disability Declaration

We hereby state that RFID function of the following equipment cannot be activated in the United States...

The RFID function of CA006 is equipped the card-mode, however, Reader/Writer mode is not equipped. In the case of card-mode only, there is no carrier wave output by the unit itself at any time or place, so no interference is transmitted within North America.

FCC ID: TYKNX6640 Model: CDMA CA006

Please contact us if you have any question regarding above.

Signature:

Yutaka *©*hiba

NEC CASIO Mobile Communications, Ltd. 1753, Shimonumabe, Nakahara-Ku

Kawasaki, 211-8666

TEL/FAX: +81-44-455-8778 / +81-44-455-8025