HCTCO,,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### Appendix D

**Contour Plots** 

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### **CDMA835 (1013CH)**

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: CDMA 835MHz FCC; Frequency: 824.7 MHz;Duty Cycle: 1:1 Medium parameters used:  $\sigma$  = 0 mho/m,  $\epsilon_r$  = 1;  $\rho$  = 0 kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006 Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011
Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -4.96 dB A/m

BWC Factor = 0.16 dB Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.97 dB

ABM1 comp = -4.96 dB A/m BWC Factor = 0.16 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -47.94 dB A/mLocation: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -17.95 dB A/m

BWC Factor = 0.16 dB

Location: -12.5, -12.5, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 38.74 dB

ABM1 comp = -17.95 dB A/m

BWC Factor = 0.16 dB

Location: -12.5, -12.5, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -56.70 dB A/m

Location: -12.5, -12.5, 3.7 mm

HCT CO, LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -12.71 dB A/m BWC Factor = 0.16 dB Location: -16.7, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor: ABM1/ABM2 = 34.17 dB

ABM1 comp = -12.71 dB A/m

BWC Factor = 0.16 dB

Location: -16.7, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:


ABM2 = -46.88 dB A/mLocation: -16.7, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 1.29 dB

BWC Factor = 10.80 dB Location: -4.3, -2.6, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### CDMA835 (384CH)

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: CDMA 835MHz FCC; Frequency: 836.52 MHz; Duty Cycle: 1:1 Medium parameters used:  $\sigma$  = 0 mho/m,  $\epsilon_r$  = 1;  $\rho$  = 0 kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -1.85 dB A/mBWC Factor = 0.15 dBLocation: -4.2, 0, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 48.94 dBABM1 comp = −1.85 dB A/m BWC Factor = 0.15 dB Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -50.79 dB A/m Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -10.68 dB A/mBWC Factor = 0.15 dB Location: -8.3, 8.3, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 47.03 dBABM1 comp = -10.68 dB A/mBWC Factor = 0.15 dBLocation: -8.3, 8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -57.71 dB A/mLocation: -8.3, 8.3, 3.7 mm

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -11.37 dB A/m BWC Factor = 0.15 dB Location: -16.7, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.85 dB

ABM1 comp = -11.37 dB A/m BWC Factor = 0.15 dB

Location: -16.7, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:


ABM2 = -53.21 dB A/m

Location: -16.7, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.60 dB

BWC Factor = 10.79 dB Location: -4.3, -0.5, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### **CDMA835 (777CH)**

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: CDMA 835MHz FCC; Frequency: 848.31 MHz;Duty Cycle: 1:1 Medium parameters used:  $\sigma$  = 0 mho/m,  $\epsilon_r$  = 1;  $\rho$  = 0 kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

## T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -3.65 dB A/mBWC Factor = 0.16 dB Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 44.37 dBABM1 comp = -3.65 dB A/m BWC Factor = 0.16 dB Location: -4.2, -4.2, 3.7 mm

#### '-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -48.03 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -21.39 dB A/m BWC Factor = 0.16 dB Location: -12.5, -8.3, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 36.60 dB ABM1 comp = -21.39 dB A/m BWC Factor = 0.16 dB Location: -12.5, -8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -57.99 dB A/mLocation: -12.5, -8.3, 3.7 mm

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -13.48 dB A/m BWC Factor = 0.16 dB

Location: -16.7, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 33.60 dB

ABM1 comp = -13.48 dB A/m BWC Factor = 0.16 dB

Location: -16.7, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -47.08 dB A/m

Location: -16.7, 0, 3.7 mm


### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 1.52 dB BWC Factor = 10.80 dB

Location: -4.3, -4.1, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### CDMA835 (384CH) Wireless charger cover

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: CDMA 835MHz FCC; Frequency: 836.52 MHz; Duty Cycle: 1:1 Medium parameters used:  $\sigma$  = 0 mho/m,  $\epsilon_r$  = 1;  $\rho$  = 0 kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -2.09 dB A/mBWC Factor = 0.15 dBLocation: -4.2, 0, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 49.01 dBABM1 comp = -2.09 dB A/mBWC Factor = 0.15 dB Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.10 dB A/m Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -11.13 dB A/mBWC Factor = 0.15 dB Location: -8.3, 8.3, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.29 dBABM1 comp = -11.13 dB A/mBWC Factor = 0.15 dBLocation: -8.3, 8.3, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -57.41 dB A/mLocation: -8.3, 8.3, 3.7 mm

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABMI comp = -10.68 dB A/m BWC Factor = 0.15 dB Location: -16.7, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.73 dB

ABM1 comp = -10.68 dB A/m BWC Factor = 0.15 dB

Location: -16.7, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -53.41 dB A/m


Location: -16.7, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 1.46 dB

BWC Factor = 10.79 dB Location: -4.2, 0, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### CDMA835 (384CH)\_Extended Battery

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: CDMA 835MHz FCC; Frequency: 836.52 MHz; Duty Cycle: 1:1 Medium parameters used:  $\sigma$  = 0 mho/m,  $\epsilon_r$  = 1;  $\rho$  = 0 kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

## T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -1.76 dB A/mBWC Factor = 0.15 dB Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 48.34 dBABM1 comp = -1.76 dB A/mBWC Factor = 0.15 dB Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -50.10 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -11.14 dB A/mBWC Factor = 0.15 dB Location: -8.3, 8.3, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.34 dBABM1 comp = -11.14 dB A/mBWC Factor = 0.15 dBLocation: -8.3, 8.3, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -57.48 dB A/mLocation: -8.3, 8.3, 3.7 mm

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -11.50 dB A/m BWC Factor = 0.15 dB

Location: -16.7, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.12 dB

ABM1 comp = -11.50 dB A/m BWC Factor = 0.15 dB

Location: -16.7, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:


ABM2 = -53.62 dB A/mLocation: -16.7, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 2.00 dB BWC Factor = 10.79 dB Location: -4.4, -3.8, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### PCS1900 (25CH)

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: PCS 1900MHz FCC; Frequency: 1851.25 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

## T–Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -3.63 dB A/mBWC Factor = 0.15 dBLocation: -4.2, 0, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.33 dBABM1 comp = -3.63 dB A/m BWC Factor = 0.15 dB Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -49.96 dB A/m Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -12.87 dB A/mBWC Factor = 0.15 dB Location: -8.3, 8.3, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 44.52 dB ABM1 comp = -12.87 dB A/m BWC Factor = 0.15 dBLocation: -8.3, 8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -57.39 dB A/mLocation: -8.3, 8.3, 3.7 mm

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -7.85 dB A/m BWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.92 dBABM1 comp = -7.85 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -49.78 dB A/mLocation: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 2.00 dB

BWC Factor = 10.79 dB Location: -4.5, 1.5, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### PCS1900 (600CH)

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: PCS 1900MHz FCC; Frequency: 1880 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

## T–Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -1.03 dB A/m

BWC Factor = 0.15 dBLocation: -4.2, 0, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 50.34 dBABM1 comp = -1.03 dB A/m

BWC Factor = 0.15 dB Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.37 dB A/m Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -12.14 dB A/m

BWC Factor = 0.15 dB Location: -8.3, 12.5, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 44.88 dB ABM1 comp = -12.14 dB A/m

BWC Factor = 0.15 dB

Location: -8.3, 12.5, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -57.01 dB A/mLocation: -8.3, 12.5, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -10.97 dB A/m BWC Factor = 0.15 dB

Location: -16.7, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.13 dB

ABM1 comp = -10.97 dB A/m BWC Factor = 0.15 dB

Location: -16.7, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -53.11 dB A/mLocation: -16.7, -4.2, 3.7 mm


### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.50 dB BWC Factor = 10.79 dB

Location: -4.3, -0.1, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### PCS1900 (1175CH )

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: PCS 1900MHz FCC; Frequency: 1908.75 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

## T–Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -2.54 dB A/mBWC Factor = 0.15 dB Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 47.80 dBABM1 comp = -2.54 dB A/mBWC Factor = 0.15 dB Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -50.34 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -11.36 dB A/m BWC Factor = 0.15 dB Location: -8.3, 8.3, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 45.96 dBABM1 comp = -11.36 dB A/mBWC Factor = 0.15 dBLocation: -8.3, 8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -57.32 dB A/mLocation: -8.3, 8.3, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -7.81 dB A/m BWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.45 dBABM1 comp = -7.81 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -49.27 dB A/mLocation: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.86 dB

BWC Factor = 10.79 dB Location: -4.3, -2.5, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### PCS1900 (600CH )\_Wireless charger cover

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: PCS 1900MHz FCC; Frequency: 1880 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 2.34 dB A/mBWC Factor = 0.15 dBLocation: 0, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.25 dBABM1 comp = 2.34 dB A/m BWC Factor = 0.15 dB Location: 0, -4.2, 3.7 mm

### T–Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -38.91 dB A/m Location: 0, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -15.99 dB A/mBWC Factor = 0.15 dB Location: -16.7, -16.7, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 36.12 dBABM1 comp = -17.99 dB A/mBWC Factor = 0.15 dBLocation: -16.7, -16.7, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -52.11 dB A/mLocation: -16.7, -16.7, 3.7 mm

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -13.52 dB A/m BWC Factor = 0.15 dB

Location: -20.8, 4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 35.66 dB

ABM1 comp = -13.52 dB A/m BWC Factor = 0.15 dB

Location: -20.8, 4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -49.18 dB A/m


Location: -20.8, 4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 1.32 dB BWC Factor = 10.79 dB Location: 2, -3.6, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### PCS1900 (600CH )\_Extended Battery

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: PCS 1900MHz FCC; Frequency: 1880 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 2.61 dB A/m BWC Factor = 0.15 dB Location: 0, 0, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.27 dBABM1 comp = 2.61 dB A/m BWC Factor = 0.15 dB Location: 0, 0, 3.7 mm

T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -38.66 dB A/m Location: 0, 0, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -15.74 dB A/mBWC Factor = 0.15 dB Location: -12.5, -20.8, 3.7 mm

-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 36.95 dBABM1 comp = -15.74 dB A/mBWC Factor = 0.15 dBLocation: -12.5, -20.8, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -52.70 dB A/mLocation: -12.5, -20.8, 3.7 mm

HCTCO,,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -9.23 dB A/mBWC Factor = 0.15 dB Location: -12.5, 4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 34.85 dBABM1 comp = -9.23 dB A/mBWC Factor = 0.15 dB Location: -12.5, 4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:


ABM2 = -44.08 dB A/m Location: -12.5, 4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 1.32 dB

BWC Factor = 10.79 dB Location: 0.8, -0.9, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

LICE.								
HCT CO.,LTD								
	LIOTATOOZETOO		TVK- IDS0507	5 . 67	Aug 6 2012			
Report No.:	HCTA1207FT03	FCC ID:	1 YK-JDS9507	Date of Issue:	Aug. 6. 2012			

### **GSM850 (128CH)**

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 850; Frequency: 824.2 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 1.82 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 35.88 dB

ABM1 comp = 1.82 dB A/m BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -34.06 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -13.47 dB A/m

BWC Factor = 0.15 dB Location: -12.5, 4.2, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 39.84 dB

ABM1 comp = -13.47 dB A/m

BWC Factor = 0.15 dB

Location: -12.5, 4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -53.31 dB A/mLocation: -12.5, 4.2, 3.7 mm

HCT CO, LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -4.64 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 31.54 dBABM1 comp = -4.64 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:


ABM2 = -36.18 dB A/mLocation: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 1.01 dB

BWC Factor = 10.79 dB Location: -3.8, -4.2, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

MCI					!
HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012
IXCDULT 110	1 1101712011 103	rccip.	1111-3003301	Date of Issue.	Aug. 0. 2012

### **GSM850 (190CH)**

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 850; Frequency: 836.6 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

## T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 1.93 dB A/m

BWC Factor = 0.16 dB

Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 36.95 dB

ABM1 comp = 1.93 dB A/m

BWC Factor = 0.16 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -35.01 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -13.46 dB A/m

BWC Factor = 0.16 dB Location: -12.5, 4.2, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.11 dB ABM1 comp = -13.46 dB A/m

BWC Factor = 0.16 dB

Location: -12.5, 4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -55.57 dB A/mLocation: -12.5, 4.2, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -4.33 dB A/mBWC Factor = 0.16 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 32.38 dBABM1 comp = -4.33 dB A/mBWC Factor = 0.16 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -36.71 dB A/mLocation: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.64 dB

BWC Factor = 10.80 dB Location: -4, -3, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

44					
HCT CO.,LTD					
HCTCO,ETD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### GSM850 (251CH)

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 850; Frequency: 848.8 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T–Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 1.82 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 34.85 dB

ABM1 comp = 1.82 dB A/m BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -33.04 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -11.77 dB A/m

BWC Factor = 0.15 dB Location: -12.5, 8.3, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 40.87 dB

ABM1 comp = -11.77 dB A/m

BWC Factor = 0.15 dB

Location: -12.5, 8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -52.64 dB A/mLocation: -12.5, 8.3, 3.7 mm

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -4.68 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 31.22 dBABM1 comp = -4.68 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -35.90 dB A/mLocation: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.95 dB

BWC Factor = 10.79 dB Location: -3.8, -4.1, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### GSM850 (190CH )\_Wireless charger cover

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 850; Frequency: 836.6 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 2.11 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 34.34 dB

ABM1 comp = 2.11 dB A/m BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -32.24 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -13.28 dB A/m

BWC Factor = 0.15 dB Location: -12.5, 4.2, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 38.74 dB

ABM1 comp = -13.28 dB A/m

BWC Factor = 0.15 dB

Location: -12.5, 4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -52.02 dB A/mLocation: -12.5, 4.2, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABMI comp = -4.38 dB A/m BWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 31.27 dBABM1 comp = -4.38 dB A/m BWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:


ABM2 = -35.65 dB A/mLocation: -12.5, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.64 dB BWC Factor = 10.79 dB Location: -3.4, -4.2, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### GSM850 (190CH )\_Extended Battery

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 850; Frequency: 836.6 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 2.24 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 34.42 dB

ABM1 comp = 2.24 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -32.18 dB A/m Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -13.38 dB A/m

BWC Factor = 0.15 dB Location: -12.5, 4.2, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 37.96 dB ABM1 comp = -13.38 dB A/m

BWC Factor = 0.15 dB

Location: -12.5, 4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.34 dB A/mLocation: -12.5, 4.2, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -4.47 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 31.05 dBABM1 comp = -4.47 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -35.52 dB A/mLocation: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.71 dB

BWC Factor = 10.79 dB Location: -3.5, -4.1, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### GSM1900 (512CH)

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 1900; Frequency: 1850.2 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 5.12 dB A/m BWC Factor = 0.16 dB

Location: 0, 0, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 37.00 dBABM1 comp = 5.12 dB A/m BWC Factor = 0.16 dB Location: 0, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -31.88 dB A/m Location: 0, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -11.69 dB A/mBWC Factor = 0.16 dB Location: -12.5, -12.5, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 39.55 dBABM1 comp = -11.69 dB A/mBWC Factor = 0.16 dB Location: -12.5, -12.5, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.24 dB A/m Location: -12.5, -12.5, 3.7 mm

HCT CO, LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -2.56 dB A/mBWC Factor = 0.16 dB Location: -8.3, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 33.63 dB ABM1 comp = -2.56 dB A/m BWC Factor = 0.16 dB Location: -8.3, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -29.92 dB A/mLocation: -8.3, 20.8, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.96 dB

BWC Factor = 10.80 dB Location: -0.5, -1.4, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### **GSM1900 (661CH )**

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 1900; Frequency: 1880 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006 Sensor-Surface: 0mm (Fix Surface) Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 1.87 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.78 dB

ABM1 comp = 1.87 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -39.91 dB A/m

Location: -4.2, -4.2, 3.7 mm

### Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -13.47 dB A/m BWC Factor = 0.15 dB Location: -12.5, 4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.96 dB

ABM1 comp = -13.47 dB A/m

BWC Factor = 0.15 dB

Location: -12.5, 4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -56.43 dB A/mLocation: -12.5, 4.2, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -7.54 dB A/m BWC Factor = 0.15 dB

Location: -16.7, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 35.51 dB

ABM1 comp = -7.54 dB A/m BWC Factor = 0.15 dB

Location: -16.7, -4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -43.05 dB A/m Location: -16.7, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.87 dB BWC Factor = 10.78 dB Location: -4.3, -4.2, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

### **GSM1900 (810CH)**

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 1900; Frequency: 1909.8 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T–Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 2.20 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.02 dB

ABM1 comp = 2.20 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -38.82 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -12.94 dB A/m

BWC Factor = 0.15 dB Location: -12.5, 4.2, 3.7 mm

### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 43.00 dB

ABM1 comp = -12.94 dB A/m

BWC Factor = 0.15 dB

Location: -12.5, 4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -55.93 dB A/mLocation: -12.5, 4.2, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -7.28 dB A/m BWC Factor = 0.15 dB Location: -16.7, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 34.69 dBABM1 comp = -7.28 dB A/m BWC Factor = 0.15 dB Location: -16.7, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -41.97 dB A/mLocation: -16.7, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.89 dB

BWC Factor = 10.79 dB Location: -4.3, -4.3, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### GSM1900 (661CH )\_Wireless charger cover

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 1900; Frequency: 1880 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 1.80 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.72 dB

ABM1 comp = 1.80 dB A/m

BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -39.92 dB A/m Location: -4.2, -4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -13.44 dB A/m

BWC Factor = 0.15 dB Location: -12.5, 4.2, 3.7 mm

#### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 43.04 dB

ABM1 comp = -13.44 dB A/m

BWC Factor = 0.15 dB

Location: -12.5, 4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -56.48 dB A/mLocation: -12.5, 4.2, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -4.73 dB A/mBWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 35.30 dB ABM1 comp = -4.73 dB A/m BWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -40.02 dB A/mLocation: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.80 dB

BWC Factor = 10.79 dB Location: -4.3, -4.7, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### GSM1900 (661CH )\_Extended Battery

DUT:C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: GSM 1900; Frequency: 1880 MHz; Duty Cycle: 1:8.30042

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006

Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011 Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 1.79 dB A/m

BWC Factor = 0.17 dB

Location: -4.2, -4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 41.74 dB

ABM1 comp = 1.79 dB A/m BWC Factor = 0.17 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -39.95 dB A/m Location: -4.2, -4.2, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -13.35 dB A/m

BWC Factor = 0.17 dB Location: -12.5, 4.2, 3.7 mm

#### -Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 43.10 dB

ABM1 comp = -13.35 dB A/m BWC Factor = 0.17 dB

Location: -12.5, 4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -56.44 dB A/mLocation: -12.5, 4.2, 3.7 mm

HCT CO, LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -4.78 dB A/mBWC Factor = 0.17 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 35.39 dBABM1 comp = -4.78 dB A/mBWC Factor = 0.17 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19–2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm


Cursor:

ABM2 = -40.17 dB A/mLocation: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1): Measurement grid: dx=10mm, dy=10mm

Cursor: Diff = 0.52 dB

BWC Factor = 10.81 dB Location: -4.3, -4.9, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA850(4132ch)

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA850; Frequency: 826.4 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 0.92 dB A/mBWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 53.89 dBABM1 comp = 0.92 dB A/m BWC Factor = 0.15 dB

Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -52.97 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -8.66 dB A/mBWC Factor = 0.15 dB Location: -8.3, 8.3, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.78 dBABM1 comp = -8.66 dB A/m BWC Factor = 0.15 dB Location: -8.3, 8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -55.44 dB A/mLocation: -8.3, 8.3, 3.7 mm

HCT CO, LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -6.60 dB A/m BWC Factor = 0.15 dB Location: -12.5, -8.3, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):
Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 45.22 dBABM1 comp = -6.60 dB A/mBWC Factor = 0.15 dB Location: -12.5, -8.3, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.81 dB A/mLocation: -12.5, -8.3, 3.7 mm


T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.66 dB

BWC Factor = 10.79 dB Location: -4.4, -3.5, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA850(4183ch)

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA850; Frequency: 836.6 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\epsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 3.12 dB A/mBWC Factor = 0.15 dB Location: 4.2. 0. 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 52.22 dBABM1 comp = 3.12 dB A/m BWC Factor = 0.15 dB Location: 4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -49.10 dB A/m Location: 4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -6.27 dB A/mBWC Factor = 0.15 dB Location: -4.2, -12.5, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.60 dBABM1 comp = -6.27 dB A/m BWC Factor = 0.15 dB Location: -4.2, -12.5, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -52.87 dB A/mLocation: -4.2, -12.5, 3.7 mm

HCT CO, LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -5.70 dB A/m BWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):
Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.98 dB ABM1 comp = -5.70 dB A/m BWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -48.68 dB A/mLocation: -12.5, -4.2, 3.7 mm


T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.67 dB

BWC Factor = 10.79 dB Location: 2.4, -1, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA850(4233ch)

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA850; Frequency: 846.6 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 0.91 dB A/mBWC Factor = 0.16 dB Location: -4.2. 0. 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 52.37 dBABM1 comp = 0.91 dB A/m BWC Factor = 0.16 dB Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.45 dB A/m Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -8.72 dB A/mBWC Factor = 0.16 dB Location: -8.3, 8.3, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.45 dB ABM1 comp = -8.72 dB A/m BWC Factor = 0.16 dB Location: -8.3, 8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

 $ABM2 = -55.17 \, dB \, A/m$ Location: -8.3, 8.3, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -5.37 dB A/m BWC Factor = 0.16 dB Location: -12.5, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.49 dBABM1 comp = -5.37 dB A/m BWC Factor = 0.16 dB Location: -12.5, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.86 dB A/mLocation: -12.5, -4.2, 3.7 mm


# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.73 dB

BWC Factor = 10.80 dB Location: -4.4, -1.5, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA850(4183ch)\_Wireless charger cover

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA850; Frequency: 836.6 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 3.14 dB A/mBWC Factor = 0.15 dB Location: 0. 0. 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 52.39 dBABM1 comp = 3.14 dB A/m BWC Factor = 0.15 dB Location: 0, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -49.25 dB A/m Location: 0, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -9.46 dB A/mBWC Factor = 0.15 dB Location: -8.3, -12.5, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.11 dBABM1 comp = -9.46 dB A/m BWC Factor = 0.15 dB Location: -8.3, -12.5, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -55.57 dB A/mLocation: -8.3, -12.5, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -5.73 dB A/m BWC Factor = 0.15 dB Location: -12.5, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.80 dBABM1 comp = -5.73 dB A/m BWC Factor = 0.15 dB

Location: -12.5, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -48.53 dB A/mLocation: -12.5, -4.2, 3.7 mm


T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.53 dB

BWC Factor = 10.79 dB Location: 1.9, -1.5, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA850(4183ch)\_Extended Battery

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA850; Frequency: 836.6 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\varepsilon_r = 1$ ;  $\rho = 0$  kg/m

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 0.98 dB A/m

BWC Factor = 0.16 dB Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 52.70 dBABM1 comp = 0.98 dB A/m

BWC Factor = 0.16 dB Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.72 dB A/m Location: -4.2, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -8.80 dB A/mBWC Factor = 0.16 dB Location: -8.3, 8.3, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 47.13 dBABM1 comp = -8.80 dB A/m BWC Factor = 0.16 dB Location: -8.3, 8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

 $ABM2 = -55.94 \, dB \, A/m$ Location: -8.3, 8.3, 3.7 mm

HCTCO,,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -8.38 dB A/m BWC Factor = 0.16 dB Location: -16.7, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):
Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 45.17 dBABM1 comp = -8.38 dB A/mBWC Factor = 0.16 dB Location: -16.7, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -53.54 dB A/mLocation: -16.7, -4.2, 3.7 mm


T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.63 dB

BWC Factor = 10.80 dB Location: -4.4, -3.1, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA1900(9262ch)

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA1900; Frequency: 1852.4 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\epsilon_r = 1$ ;  $\rho = 0$  kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 3.32 dB A/mBWC Factor = 0.16 dB

Location: 0, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ĀBM1/ABM2 = 52.39 dB ABM1 comp = 3.32 dB A/m BWC Factor = 0.16 dB Location: 0, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -49.07 dB A/m Location: 0, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -7.37 dB A/mBWC Factor = 0.16 dB Location: -4.2, 4.2, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.35 dBABM1 comp = -7.37 dB A/m BWC Factor = 0.16 dB Location: -4.2, 4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -53.72 dB A/mLocation: -4.2, 4.2, 3.7 mm

HCTCO,,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -8.70 dB A/m BWC Factor = 0.16 dB Location: -16.7, -4.2, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.60 dBABM1 comp = -8.70 dB A/mBWC Factor = 0.16 dB Location: -16.7, -4.2, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.31 dB A/mLocation: -16.7, -4.2, 3.7 mm


# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.58 dB

BWC Factor = 10.79 dB Location: 2.2, -2.4, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA1900(9400ch)

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA1900; Frequency: 1880 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\epsilon_r = 1$ ;  $\rho = 0$  kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 0.48 dB A/mBWC Factor = 0.16 dB Location: -4.2. 0. 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 51.70 dBABM1 comp = 0.48 dB A/mBWC Factor = 0.16 dB Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.22 dB A/m Location: -4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -9.02 dB A/mBWC Factor = 0.16 dB Location: -8.3, 8.3, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.35 dBABM1 comp = -9.02 dB A/m BWC Factor = 0.16 dB Location: -8.3, 8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -55.37 dB A/mLocation: -8.3, 8.3, 3.7 mm

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -6.63 dB A/m BWC Factor = 0.16 dB Location: -12.5, -8.3, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):
Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.65 dBABM1 comp = -6.63 dB A/mBWC Factor = 0.16 dB Location: -12.5, -8.3, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -49.28 dB A/mLocation: -12.5, -8.3, 3.7 mm


T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.64 dB

BWC Factor = 10.79 dB Location: -4.3, -0.5, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA1900(9538ch)

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA1900; Frequency: 1907.6 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\epsilon_r = 1$ ;  $\rho = 0$  kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 3.13 dB A/mBWC Factor = 0.16 dB Location: 0. 0. 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 52.12 dBABM1 comp = 3.13 dB A/m BWC Factor = 0.16 dB Location: 0, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -48.99 dB A/m Location: 0, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -8.32 dB A/mBWC Factor = 0.16 dB Location: -4.2, -8.3, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.80 dBABM1 comp = -8.32 dB A/mBWC Factor = 0.16 dB Location: -4.2, -8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -55.12 dB A/mLocation: -4.2, -8.3, 3.7 mm

HCT CO, LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -5.70 dB A/m BWC Factor = 0.16 dB Location: -12.5, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):
Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.80 dB ABM1 comp = -5.70 dB A/m BWC Factor = 0.16 dB Location: -12.5, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -48.50 dB A/mLocation: -12.5, -4.2, 3.7 mm


T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.62 dB

BWC Factor = 10.80 dB Location: 2.1, -1.3, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA1900(9400ch)\_Wireless charger cover

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA1900; Frequency: 1880 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\epsilon_r = 1$ ;  $\rho = 0$  kg/m<sup>3</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

- Probe: AM1DV2 1013; ; Calibrated: 18/04/2006
- Sensor-Surface: 0mm (Fix Surface)

- Electronics: DAE4 Sn869; Calibrated: 22/09/2011
  Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial
  Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 3.16 dB A/m BWC Factor = 0.16 dB

Location: 4.2. 0. 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 52.29 dBABM1 comp = 3.16 dB A/m BWC Factor = 0.16 dB Location: 4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -49.13 dB A/m Location: 4.2, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -8.27 dB A/mBWC Factor = 0.16 dB Location: -4.2, -8.3, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.82 dBABM1 comp = -8.27 dB A/mBWC Factor = 0.16 dB Location: -4.2, -8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -55.09 dB A/mLocation: -4.2, -8.3, 3.7 mm

HCT CO.,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -8.62 dB A/m BWC Factor = 0.16 dB Location: -16.7, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.78 dBABM1 comp = -8.62 dB A/m BWC Factor = 0.16 dB Location: -16.7, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.40 dB A/mLocation: -16.7, -4.2, 3.7 mm

T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):


Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.58 dB

BWC Factor = 10.80 dB

Location: 2.5, -1.4, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m

HCTCO,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

#### WCDMA1900(9400ch)\_Extended Battery

DUT: C811; Type: Bar; Serial: #1 Procedure Name: General Scans

Communication System: WCDMA1900; Frequency: 1880 MHz; Duty Cycle: 1:1

Medium parameters used:  $\sigma = 0$  mho/m,  $\epsilon_r = 1$ ;  $\rho = 0$  kg/m<sup>2</sup>

Phantom section: TCoil Section

#### DASY5 Configuration:

Probe: AM1DV2 - 1013; ; Calibrated: 18/04/2006 Sensor-Surface: 0mm (Fix Surface)

Electronics: DAE4 Sn869; Calibrated: 22/09/2011
Phantom: HAC Test Arch with AMCC; Type: SD HAC P01 BA; Serial

Measurement SW: DASY52, Version 52.8 (0); SEMCAD X Version 14.6.4 (4989)

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = 3.24 dB A/mBWC Factor = 0.16 dB

Location: 0, 0, 3.7 mm

#### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 52.71 dB ABM1 comp = 3.24 dB A/m BWC Factor = 0.16 dB

Location: 0, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -49.47 dB A/m

Location: 0, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Signal(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1 comp = -8.28 dB A/m BWC Factor = 0.16 dB

Location: -4.2, -8.3, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 46.66 dB

ABM1 comp = -8.28 dB A/m

BWC Factor = 0.16 dB

Location: -4.2, -8.3, 3.7 mm

## T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/y (transversal) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -54.94 dB A/m

Location: -4.2, -8.3, 3.7 mm

HCTCO,,LTD					
Report No.:	HCTA1207FT03	FCC ID:	TYK-JDS9507	Date of Issue:	Aug. 6. 2012

Cursor:

ABM1 comp = -8.82 dB A/m BWC Factor = 0.16 dB Location: -16.7, 0, 3.7 mm

# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM SNR(x,y,z) (13x13x1): Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM1/ABM2 = 42.49 dBABM1 comp = -8.82 dB A/mBWC Factor = 0.16 dB Location: -16.7, 0, 3.7 mm

### T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/x (longitudinal) (2007) 4.2mm 50 x 50/ABM Noise(x,y,z) (13x13x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

ABM2 = -51.32 dB A/mLocation: -16.7, 0, 3.7 mm


# T-Coil scan (scan for ANSI C63.19-2007 & 2011 compliance)/General Scans/z (axial) wideband at best S/N/ABM Freq Resp(x,y,z,f) (1x1x1):

Measurement grid: dx=10mm, dy=10mm

Cursor:

Diff = 0.64 dB

BWC Factor = 10.80 dB Location: 2, -1, 3.7 mm



0 dB = 1.000A/m = 0 dB A/m