
Test report No. : 31GE0227-SH-02

Page : 1 of 2

Issued date : March 25, 2011 FCC ID : TYK-BHJ3994

APPENDIX 1: Photographs of test setup

Radiated emission



Rear (below 30MHz)



1-22-3 Megumigaoka Hiratsuka-shi Kanagawa-ken 259-1220 JAPAN telephone: +81 463 50 6400 / facsimile: +81 463 50 6401

Test report No. : 31GE0227-SH-02

Page : 2 of 2

Issued date : March 25, 2011 FCC ID : TYK-BHJ3994

Worst Case Position

	Horizontal	Vertical
Carrier	X	Z
Spurious emission (9k-30MHz)	Z	Y
Spurious emission (30M-1GHz)	Z	X



