


Annex B of test report R52105 Edition 1 EUT: EXPLORER Bluetooth Handset Manufacturer: Avaya-Tenovis GmbH & Co. KG



52105_5.jpg EXPLORER Bluetooth handset, internal view



Manufacturer: Avaya-Tenovis GmbH & Co. KG



52105_15.jpg EXPLORER Bluetooth handset, PCB, top view



Manufacturer: Avaya-Tenovis GmbH & Co. KG



52105_18.jpg EXPLORER Bluetooth handset, PCB, top view, shielding removed

Examiner: Thomas KÜHN Date of issue: 02 February 2006 page 3 of 8




Manufacturer: Avaya-Tenovis GmbH & Co. KG



52105_14.jpg EXPLORER Bluetooth handset, PCB, bottom view



Manufacturer: Avaya-Tenovis GmbH & Co. KG




52105_16.jpg EXPLORER Bluetooth handset, PCB, bottom view, display removed

Examiner: Thomas KÜHN Date of issue: 02 February 2006 page 5 of 8



Annex B of test report R52105 Edition 1 EUT: EXPLORER Bluetooth Handset Manufacturer: Avaya-Tenovis GmbH & Co. KG




52105_13.jpg EXPLORER Bluetooth handset, sample with antenna connector, PCB, top

view

Examiner: Thomas KÜHN Date of issue: 02 February 2006 page 6 of 8




Manufacturer: Avaya-Tenovis GmbH & Co. KG



52105_2.jpg EXPLORER Bluetooth handset Charger, PCB bottom view



Manufacturer: Avaya-Tenovis GmbH & Co. KG



52105_1.jpg EXPLORER Bluetooth handset Charger, PCB top view

Examiner: Thomas KÜHN Date of issue: 02 February 2006 page 8 of 8