





Inside View of The EUT



Report no. ETLE060201.037, Page 1 of 10


Head Office : # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel : 82-2-858-0786 Fax : 82-2-858-0788







Component side view of Main board




Report no. ETLE060201.037, Page 2 of 10

Head Office : # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel : 82-2-858-0786 Fax : 82-2-858-078





Solder side view of Main board



Report no. ETLE060201.037, Page 3 of 10

Head Office : # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel : 82-2-858-0786 Fax : 82-2-858-0788










Inside View of The LNB TUNER





Report no. ETLE060201.037, Page 4 of 10

Head Office : # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel : 82-2-858-0786 Fax : 82-2-858-0788





Component side view of Power board




Report no. ETLE060201.037, Page 5 of 10

Head Office: # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel: 82-2-858-0786





Solder side view of Power board



Report no. ETLE060201.037, Page 6 of 10


Head Office: # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel: 82-2-858-0786








Component side view of Front Board



Solder side view of Front Board



Report no. ETLE060201.037, Page 7 of 10

Head Office : # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel : 82-2-858-0786 Fax : 82-2-858-0788










Inside View of The EUT of RF Modulator





Report no. ETLE060201.037, Page 8 of 10

Head Office : #371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel : 82-2-858-0786 Fax : 82-2-858-0788







View of Bottom cover



View of Top cover



Report no. ETLE060201.037, Page 9 of 10

Head Office: # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel: 82-2-858-0786 Fax: 82-2-858-078







View of Front Cover



Head Office: # 371-51 Kasan-Dong, Keumcheon-ku, Seoul, 153-803, Korea Tel: 82-2-858-0786 Fax: 82-2-858-0788