Untertürkheimer Str. 6-10, 66117 Saarbruecken Phone: +49 (0) 681 598-0 RSC-Laboratory Phone: +49 (0) 681 598-0

Fax: -9075






7 Annex C: External Photographs of the Equipment

Photo 1:








Phone: +49 (0) 681 598-0 Fax: -9075 **RSC-Laboratory** Phone: +49 (0) 681 598-0 Fax: -9075

Annex to Test report no.: 4-2170-01-03/06 Page 24 of 49 Date: 2006-08-14

Photo 2:








Fax: -9075 **RSC-Laboratory** Phone: +49 (0) 681 598-0 Fax: -9075

Annex to Test report no.: 4-2170-01-03/06 Page 25 of 49 Date: 2006-08-14

Photo 3:







Fax: -9075


RSC-Laboratory Phone: +49 (0) 681 598-0 Fax: -9075

Annex to Test report no.: 4-2170-01-03/06 Date: 2006-08-14 Page 26 of 49

Photo 4:



CETECOM ICT Services GmbH Untertürkheimer Str. 6-10, 66117 Saarbruecken Phone: +49 (e



Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0

Fax: -9075 Fax: -9075



Photo 5:










Phone: +49 (0) 681 598-0 Fax: -9075 **RSC-Laboratory** Phone: +49 (0) 681 598-0 Fax: -9075

Page 28 of 49 Annex to Test report no.: 4-2170-01-03/06 Date: 2006-08-14

Photo 6:






Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075














Fax: -9075

RSC-Laboratory Phone: +49 (0) 681 598-0 Fax: -9075

Annex to Test report no.: 4-2170-01-03/06 Date: 2006-08-14 Page 30 of 49

Photo 8:





Fax: -9075 Phone: +49 (0) 681 598-0 Fax: -9075



Annex to Test report no.: 4-2170-01-03/06 Page 31 of 49 Date: 2006-08-14

Photo 9:

