## 6.4.4 Photos of Conduction Measuring Setup

Model: MD6430 Mode: Base Charging





Model: MD6430 Mode: Base On Line





## **6.13.4 Photos of Radiation Measuring Setup**

Model MD6430





Model: MD6430 Mode: Base On Line



