
## 1. External Photograph of EUT

Model Name: ZB-100

Report No.: EP910601



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : 1 of 21



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : 2 of 21



Model Name: ZB-100

Report No.: EP910601



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : 3 of 21





Report No.: EP910601




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110

Page Number : 4 of 21



Report No.: EP910601



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : 5 of 21

Model Name: ZB-100

Report No.: EP910601



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : 6 of 21

## 2. **Photograph of Accessory**

Model Name: ZB-100

Report No.: EP910601



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110

Page Number : 7 of 21

Issued Date : Dec. 28, 2009

Report Version : Rev. 01



Model Name: ZB-100

Report No.: EP910601




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110

Page Number : 8 of 21


Issued Date : Dec. 28, 2009

Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : 9 of 21





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : 10 of 21 Issued Date : Dec. 28, 2009

Report Version : Rev. 01