3. Internal Photograph of EUT


Brand Name: HOLUX / Model Name: GR-520

Report No.: EP070125




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 17 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01

Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 18 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01



Brand Name: HOLUX / Model Name: GR-520

70 60 50 40 30 20

10 mm


00 07 01 00 08 02 09 09 01 00 07 01

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 19 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01



Report No.: EP070125




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101

Page Number : 20 of 32 Report Issued Date : Jul. 16, 2010 Report Version : Rev. 01



Report No.: EP070125




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101

Page Number : 21 of 32 Report Issued Date : Jul. 16, 2010 Report Version : Rev. 01

SPORTION LAB. Photographs of EUT

Brand Name: HOLUX / Model Name: GR-520


Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 22 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01




Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 23 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01




Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101

Page Number : 24 of 32 Report Issued Date : Jul. 16, 2010 Report Version : Rev. 01


Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 25 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01





Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101

Page Number : 26 of 32 Report Issued Date : Jul. 16, 2010 Report Version : Rev. 01






SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 27 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01


Report No.: EP070125



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 28 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01


Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 29 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01





Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101

Page Number : 30 of 32 Report Issued Date : Jul. 16, 2010 Report Version : Rev. 01





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 31 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01

Report No.: EP070125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB101 Page Number : 32 of 32
Report Issued Date : Jul. 16, 2010
Report Version : Rev. 01