# APPENDIX B. Internal Photographs of EUT



## SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : B1 OF B8

Report Issued Date : May 31, 2007

Report Version : Rev.01

REPORT NO.: FG742506-01






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : B2 OF B8
Report Issued Date : May 31, 2007


Report Version : Rev.01





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : B3 OF B8
Report Issued Date : May 31, 2007
Report Version : Rev.01






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

: B4 OF B8 Page Number Report Issued Date : May 31, 2007

Report Version : Rev.01






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : B5 OF B8
Report Issued Date : May 31, 2007

Report Version : Rev.01






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255

: B6 OF B8 Page Number Report Issued Date : May 31, 2007

Report Version : Rev.01






TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : B7 OF B8

Report Issued Date : May 31, 2007

Report Version : Rev.01





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : B8 OF B8
Report Issued Date : May 31, 2007
Report Version : Rev.01