


Report No.: FG910601

Appendix B. Setup Photographs

<Radiated Emission>



Front View



Rear View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : B1 of B2
Report Issued Date : Dec. 28, 2009
Report Version : Rev. 01





Report No.: FG910601



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2I-ZB110 Page Number : B2 of B2
Report Issued Date : Dec. 28, 2009
Report Version : Rev. 01