
Appendix C. Set up Photograph

Spurious Radiation



Report No.: FG742506-01

FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C1
Report Issued Date : May 31, 2007
Report Version : Rev. 01