



# **Appendix A. Test Photos**



Radiated Below 1GHzTest\_Ant 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A17

Report Version : Rev. 01



FCC Test Report No.: FR341809





Radiated Below 1GHzTest\_Ant 2




SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A17







Radiated Below 1GHzTest\_Ant 3



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A17







Radiated Above 1GHzTest\_Ant 1




SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A4 of A17




## FCC Test Report

#### Radiated Above 1GHzTest\_Ant 1



Radiated Above 1GHzTest\_Ant 1



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A5 of A17


Report Version

: Rev 01










Radiated Above 1GHzTest\_Ant 2



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A6 of A17

Report Version










Radiated Above 1GHzTest\_Ant 2



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No.

: A7 of A17

Report Version










Radiated Above 1GHzTest\_Ant 3



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A8 of A17

Report Version






Radiated Above 1GHzTest\_Ant 3



Radiated Above 1GHzTest\_Ant 3



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A9 of A17

Report No. : FR341809



FCC Test Report No.: FR341809





Conducted Test\_Ant 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No.

: A10 of A17

Report Version




FCC Test Report No. : FR341809

### Conducted Test\_Ant 1



Conducted Test\_Ant 1




SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A11 of A17





Conducted Test\_Ant 1



Conducted Test\_Ant 2



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No.

: A12 of A17

Report Version

: Rev. 01





Test Report No. : FR341809

#### Conducted Test\_Ant 2



Conducted Test\_Ant 2



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No.

: A13 of A17

Report Version







Conducted Test\_Ant 2



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A14 of A17










Conducted Test\_Ant 3



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No.

: A15 of A17

Report Version





Conducted Test\_Ant 3



Conducted Test\_Ant 3



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A16 of A17


Report Version : Rev 01



# FCC Test Report

#### Conducted Test\_Ant 3

Report No. : FR341809



SPORTON INTERNATIONAL INC. Page No. : A17 of A17 TEL: 886-3-3273456 Report Version : Rev. 01

FAX: 886-3-3270973