


## Appendix C. Setup Photographs

## **Adapter Mode**

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : C1 of C2
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report No.: FR5D2212E2

Report Template No.: BU5-FR15CWL Version 1.2



## FCC RF Test Report

## **POE Mode**

LF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : C2 of C2
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report No.: FR5D2212E2

Report Template No.: BU5-FR15CWL Version 1.2