Test Photos Report No.: FR371305-01C2

## **Appendix A. TEST PHOTOS**

### 1 Photographs of Conducted Emissions Test Configuration

### Dipole antenna



FRONT VIEW



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



Report No.: FR371305-01C2



**CLOSE VIEW** 



**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01







Report No.: FR371305-01C2

#### **Photographs of Radiated Emissions Test Configuration** 2

### Dipole antenna



FRONT VIEW




**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A3 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01



Report No.: FR371305-01C2



**CLOSE VIEW** 



**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



# **Appendix A. Test Photos**

### **DFS Test**



**DFS Test** 



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A1

Report Version

: Rev. 01

Report No.: FZ371305-01