


SPORTON International Inc. Page No. : 8 of 23





FCC ID: U2M-PCE4553AH

FCC ID: U2M-PCE3203AH



SPORTON International Inc. Page No. : 9 of 23








SPORTON International Inc. Page No. : 10 of 23








SPORTON International Inc. Page No. : 11 of 23







SPORTON International Inc. Page No. : 12 of 23







SPORTON International Inc. Page No. : 13 of 23








SPORTON International Inc. Page No. : 14 of 23










SPORTON International Inc. Page No. : 15 of 23








SPORTON International Inc. Page No. : 16 of 23










SPORTON International Inc. Page No. : 17 of 23

















SPORTON International Inc. Page No. : 19 of 23







SPORTON International Inc. Page No. : 20 of 23











SPORTON International Inc. Page No. : 21 of 23



## Photographs of Module

FCC ID: U2M-PCE3203AH







SPORTON International Inc. Page No. : 22 of 23



REPORT No.: EP382718

FCC ID: U2M-PCE4553AH





SPORTON International Inc. Page No. : 23 of 23