


Appendix A. TEST PHOTOS

1 Photographs of Conducted Emissions Test Configuration




FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01






CLOSE VIEW



Ant 1 (1002302)

SPORTON INTERNATIONAL INC. Page No. : A2 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01





Ant 3 (1002303)




Ant 5 (1002304)


SPORTON INTERNATIONAL INC. Page No. : A3 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01



2 Photographs of Radiated Emissions Test Configuration




FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01





CLOSE VIEW




CLOSE VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01






Ant 1 (1002302)



Ant 3 (1002303)

SPORTON INTERNATIONAL INC. Page No. : A6 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01





Ant 5 (1002304)

SPORTON INTERNATIONAL INC. Page No. : A7 of A7 TEL: 886-3-327-3456 Report Version : Rev. 01