


Appendix A. Test Photos

Radiated Test



Radiated Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A4

Report Version

: Rev. 01


Report No. : FR3N0541-01







Radiated Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A4

Report Version

: Rev. 01

Report No. : FR3N0541-01







Radiated Test



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A4

Report No.: FR3N0541-01

Report Version : Rev. 01



FCC C2PC Test Report



Report No. : FR3N0541-01

SPORTON INTERNATIONAL INC. Page No. : A4 of A4 TEL: 886-3-3273456 Report Version : Rev. 01

FAX: 886-3-3270973