


Appendix D. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D1 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report No.: FR5D2212D2

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.2



Report No.: FR5D2212D2


<Radiated Emission>

EUT with Adapter Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D2 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.2

CC Test Report No. : FR5D2212D2

EUT with POE Mode

LF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D3 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.2