
Test Photos Report No. : FR371207

## **Appendix A. TEST PHOTOS**

## 1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



Report No.: FR371207



**CLOSE VIEW** 




**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01




**Report No.: FR371207** 

## **Photographs of Radiated Emissions Test Configuration** 2



FRONT VIEW



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A3 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR371207

**CLOSE VIEW** 



**CLOSE VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A4 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01