


Appendix C. Setup Photographs

Y Plane with Adapter Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : C1 of C2
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report No.: FR5D2212E1


Report Template No.: BU5-FR15CWL Version 1.2



FCC RF Test Report

Y Plane with POE Mode

LF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : C2 of C2
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report No.: FR5D2212E1

Report Template No.: BU5-FR15CWL Version 1.2