




Appendix A. Test Photos





Radiated Test_Ant 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No.

: A1 of A12

Report Version

: Rev. 01

Report No.: FR370334






Radiated Test_Ant 1



Radiated Test_Ant 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A12


Report Version : R

: Rev. 01










Radiated Test_Ant 2



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A12







Radiated Test_Ant 2



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A4 of A12




FCC Test Report

Report No.: FR370334





Radiated Test_Ant 3



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A5 of A12







Radiated Test_Ant 3




SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A6 of A12

: Rev. 01

Report Version






Conducted Test_Ant 1



Conducted Test_Ant 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A7 of A12





Conducted Test_Ant 1



Conducted Test_Ant 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A8 of A12

Report Version

: Rev. 01






Conducted Test_Ant 2



Conducted Test_Ant 2



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A9 of A12


Report Version

: Rev. 01










Conducted Test_Ant 2



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A10 of A12





Conducted Test_Ant 3



Conducted Test_Ant 3



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A11 of A12







Conducted Test_Ant 3



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A12 of A12