


# Appendix D. Setup Photographs

# <Conducted Emission>

#### Mode 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D1 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report No.: FR5D2212B2

Report Template No.: BU5-FR15EWL AC MA Version 1.3




Report No. : FR5D2212B2

## <Radiated Emission>

#### **Adapter Mode**

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D2 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC MA Version 1.3



CC Test Report No.: FR5D2212B2

## **POE Mode**

LF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D3 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC MA Version 1.3