
Test Photos Report No. : FR371206

Appendix A. TEST PHOTOS

1 Photographs of Conducted Emissions Test Configuration



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01



Report No. : FR371206

CLOSE VIEW





CLOSE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01




Test Photos Report No. : FR371206

2 Photographs of Radiated Emissions Test Configuration



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A3 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01



Report No. : FR371206

CLOSE VIEW





CLOSE VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A4 TEL: 886-3-327-3456 Report Version : Rev. 01