



Appendix A. Test Photos

Radiated Test



Radiated Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A1 of A7

Report Version

: Rev. 01

Report No.: FR3N0541





Report No.: FR3N0541

Radiated Test



Radiated Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A2 of A7


Report Version : Rev. 01






Report No.: FR3N0541





Radiated Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A3 of A7
Report Version : Rev. 01



Radiated Test

Report No.: FR3N0541


SPORTON INTERNATIONAL INC. Page No. : A4 of A7 TEL: 886-3-3273456 Report Version : Rev. 01

FAX: 886-3-3270973






Conducted Test



Conducted Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A5 of A7

Report Version : Rev. 01

Report No.: FR3N0541






Report No. : FR3N0541





Conducted Test



SPORTON INTERNATIONAL INC.


TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A6 of A7

Report Version : Rev. 01





Report No. : FR3N0541



Conducted Test



SPORTON INTERNATIONAL INC.

TEL: 886-3-3273456 FAX: 886-3-3270973 Page No. : A7 of A7
Report Version : Rev. 01