


# Appendix D. Setup Photographs

## <Conducted Emission>

#### Mode 1



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D1 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report No.: FR5D2212A2

Report Template No.: BU5-FR15CWL MA Version 1.2



#### Report No.: FR5D2212A2

### <Radiated Emission>

#### **EUT with Adapter Mode**

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D2 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 1.2

### Report No.: FR5D2212A2

#### **EUT with POE Mode**

LF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U2M-CAP7252AG Page Number : D3 of D3
Report Issued Date : Sep. 21, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL MA Version 1.2