Scott McCutchan

From: Scott McCutchan [scott@celectronics.com]

Sent: Friday, July 25, 2008 3:42 PM

To: 'kyle@celectronics.com'

Cc: 'mike@celectronics.com'

Subject: FCC ID: U2QTXRX10002000

Mr. Fujimoto:

In order for processing of this certification application (FCC ID: U2QTXRX10002000) to continue, the following issue(s) will have to be addressed:

- 1) Section 4.1 of the test report indicates that the device turns off immediately after the button is released. As described in the application, the device seems to be automatically activated. Please clarify; and indicate how the device complies with section 15.231(a)(2) of the FCC rules.
- 2) The 4th harmonic of the transmitter (1672 MHz) falls within a restricted band of operation, but the limit used does not reflect this. Please correct the report.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website. Your correspondence number is U2QTXRX10002000-1.

Best regards,

Scott McCutchan Operations Manager Compatible Electronics TCB