

Use only antennas and cables aupplied with this equipment. Others could severally degrade performance and yiolate FCC rules >> Warning! << PhoneLink Wireless Dial Tone Extender TriLink Wireless, Ins. Fate, Texas Model Number > PLB300 Serial Number > This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) This device must not cause harmful interference, and (2) This device must assept any interference received, including interference that may cause undestrable operation. FCC ID: 123456789 Base Unit - Connect to Phone Company Line 2 Ring / Off-Hook 2 Wireless Signal Phone Company Power (9-12406)



PILOT TECHNOLOGIES, INC. SCOTT HAMMOND President P.O. Box 2073 Rockwall, TX 75087 (972) 772-9737 Fax: (972) 772-9734 email: shammond@airmail.net

