

Report No. : FA0N0835-01

Appendix E. **Test Setup Photos**





Right Cheek

Right Tilted





Left Cheek

Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U46-M570

Page Number : E1 of E1 Report Issued Date: May 24, 2011 Report Version : Rev. 01