


Report No. : FA080435

Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958

FCC ID: U46-D3

Page Number : D1 of D1
Report Issued Date : Sep. 30, 2010
Report Version : Rev. 01



Report No.: FA080435

Test Setup Photos Appendix E.



Direct Laptop Plug-in for USB Configuration 1 (Horizontal Up with Phantom 5 mm Gap)



USB Cable Plug-in for USB Configuration 2 (Horizontal Down with Phantom 5 mm Gap)



USB Cable Plug-in for USB Configuration 3 (Vertical Front with Phantom 5 mm Gap)



Direct Laptop Plug-in USB Configuration 4 (Vertical Back with Phantom 5 mm Gap)



Direct Laptop Plug-in for USB Configuration 5 (Tip Mode with Phantom 5 mm Gap)

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-D3

Page Number : E1 of E1 Report Issued Date: Sep. 30, 2010

Report Version : Rev. 01