

## Appendix B. Setup Photographs


<Radiated Emission>

E1 Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2070 Page Number : B1 of B2
Report Issued Date : Jul. 26, 2012
Report Version : Rev. 02


Report No. : FG242601






E2 Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2070 Page Number : B2 of B2
Report Issued Date : Jul. 26, 2012
Report Version : Rev. 02

Report No.: FG242601