## 1. External Photograph of EUT

Brand Name: OPEN MOBILE\PUBLIC MOBILE / Model Name: M570

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 1 of 26
Report Issued Date : Dec. 09, 2010

Report Version : Rev. 01



Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 2 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 3 of 26
Report Issued Date : Dec. 09, 2010

Report Version : Rev. 01

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 4 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570

Page Number : 5 of 26 Report Issued Date : Dec. 09, 2010

Report Version : Rev. 01

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 6 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

## 2. Photograph of Accessory

Brand Name: OPEN MOBILE\PUBLIC MOBILE / Model Name: M570

Report No.: EP0N0835

## **List of Accessory:**

| Specification of Accessory |                  |                                                    |
|----------------------------|------------------|----------------------------------------------------|
| IAC Adapter                | Brand Name       | BI                                                 |
|                            | Model Name       | BI05-050060-BDU                                    |
| IRattery                   | Brand Name       | Not stated                                         |
|                            | Model Name       | Not stated                                         |
| USB Cable                  | Signal Line Type | 1.21 meter non-shielded cable without ferrite core |

**Remark:** For accessories equipped with this EUT, please refer to the following photos.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 7 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 8 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 9 of 26 Report Issued Date : Dec. 09, 2010

Report Version : Rev. 01

Report No.: EP0N0835




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 10 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 11 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 12 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 13 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 14 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 15 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01

Report No.: EP0N0835



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-M570 Page Number : 16 of 26
Report Issued Date : Dec. 09, 2010
Report Version : Rev. 01