

Report No. : FA0D0329

Appendix D. Product Photos










TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2030 Page Number : D1 of D1
Report Issued Date : Jan. 21, 2011
Report Version : Rev. 02




Report No.: FA0D0329

Appendix E. Test Setup Photos



Right Cheek









Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2030 Page Number : E1 of E1
Report Issued Date : Jan. 21, 2011
Report Version : Rev. 02