



Report No. : FA242601

Appendix D. Product Photos



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2070

Page Number : D1 of D3 Report Issued Date: Jul. 26, 2012 : Rev. 03 Report Version



FCC SAR Test Report






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2070 Page Number : D2 of D3
Report Issued Date : Jul. 26, 2012
Report Version : Rev. 03

Report No. : FA242601



Report No. : FA242601

Antenna Location:



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2070 Page Number : D3 of D3
Report Issued Date : Jul. 26, 2012
Report Version : Rev. 03




Report No. : FA242601

Appendix E. **Test Setup Photos**



Right Cheek

Right Tilted







Left Tilted



Front of the DUT with Phantom 1.5 cm Gap (Headset)




Back of the DUT with Phantom 1.5 cm Gap (Headset)


SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2070

Page Number : E1 of E2 Report Issued Date: Jul. 26, 2012 Report Version : Rev. 03








Right Cheek

Right Tilted





Left Cheek

Left Tilted

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: U46-CDM2070 Page Number : E2 of E2
Report Issued Date : Jul. 26, 2012
Report Version : Rev. 03