

Client: LevelStar, LLC Models: EI-30, EIB-30, IBP-30 Standards: FCC 15.247 & RSS-210 FCC/IC ID: U48-EI0001/6999A-EI0001 Report #: 2007137

Appendix L: **Internal Photographs**




Photograph 9: Interior View

Client: LevelStar, LLC
Models: EI-30, EIB-30, IBP-30
Standards: FCC 15.247 & RSS-210
FCC/IC ID: U48-EI0001/6999A-EI0001




Photograph 10: PCB's Top View

Client: LevelStar, LLC
Models: EI-30, EIB-30, IBP-30
Standards: FCC 15.247 & RSS-210
FCC/IC ID: U48-EI0001/6999A-EI0001
Report #: 2007137




Photograph 11: **PCB's Back View**

Client: LevelStar, LLC
Models: EI-30, EIB-30, IBP-30
Standards: FCC 15.247 & RSS-210
FCC/IC ID: U48-EI0001/6999A-EI0001




Photograph 12: 802.11b Module Top View with Shield

Client: LevelStar, LLC
Models: EI-30, EIB-30, IBP-30
Standards: FCC 15.247 & RSS-210
FCC/IC ID: U48-EI0001/6999A-EI0001



Photograph 13: 802.11b Module Top View without Shield

Client: LevelStar, LLC
Models: EI-30, EIB-30, IBP-30
Standards: FCC 15.247 & RSS-210
FCC/IC ID: U48-EI0001/6999A-EI0001



Photograph 14: 802.11b Module Bottom View




Report No: EF/2006/10012 **Issue Date: Apr. 24, 2006**

External of Bluetooth



External of Bluetooth



The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan. / 台北縣五股工業區五工路134號
t (886-2) 2299-3939

f (886-2) 2298-2698

www.sgs.com.tw



FCC ID: POOWML-C46

Report No: EF/2006/10012 **Issue Date: Apr. 24, 2006**

Bluetooth without Shields

