





Reassessment Application Letter

Datalogic ADC S.r.l Via San Vitalino, 13 40012 Calderara di Reno Italy.

> Attn: Reviewing Engineer Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Request for Reassessment / Class 2 Permissive change

Model: JOYA TOUCH A6

FCC ID: U4GJTAWB

IC: 3862E-JTAWB

HVIN: JTAWB GUN

HVIN: JTAWB HH

To whom it may concern:

We hereby request a Class II Permissive Change for the above listed device to cover following performed modifications:

RF output power decrease

- ✓ The RF power decrease is implemented through a different software configuration
- ✓ There is no hardware design change that decreases the output power
- ✓ The maximum output power rating of the original authorization does not change

The RF power decrease details are summarized in the table below:



www.datalogic.com





WLAN Technology	Channel	SW Power decrease	New Test report	Original test report
802.11 g			CETECOM_TR18-1- 0100501T01a	
	11	2,5 dB	CETECOM_TR18-1- 0100501T01a_A1	WT178003543
			CETECOM_TR18-1- 0100501T01a	
802.11 n	11	2,5 dB	CETECOM_TR18-1- 0100501T01a_A1	WT178003543

Yours sincerely,

⇔DATALOGIC

Ruggers Ocioffs

Ruggero Cacioppo

Product Quality Leader