



**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5180MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C /54%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
			0







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02 ~ 06	Temp./Hum.	24°C/54 ~ 55%
Mode	802.11n-HT20	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
			0







**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C /54%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0







**Audix Technology Corp.**  
 No. 53-11, Dingfu, Linkou, Dist.,  
 New Taipei City244, Taiwan

Tel: +886 2 26099301  
 Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5320MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5500MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (Via Notebook PC)
			0







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5600MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/09/26 ~ 10/02	Temp./Hum.	24 ~ 25°C /54 ~ 55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5745MHz
		Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5785MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC) 0		






**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan


Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/09/26 ~ 10/02	Temp./Hum.	24 ~ 25°C /54 ~ 55%
Mode	802.11n-HT20	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5825MHz
Simultaneous Factor 10 log(n)	(Note: "n" is antenna number)		
			0



**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan


Tel: +886 2 26099301  
Fax: +886 2 26099303




**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5190MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	I
Cable Loss	4.2dB	Frequency	TX 5230MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5270MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC) 0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2A
Cable Loss	4.2dB	Frequency	TX 5310MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5510MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	3		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5590MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/54%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	4.2dB	Frequency	TX 5670MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	Test Voltage DC 3.3V (Via Notebook PC)		
	0		







**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/09/26 ~ 10/02	Temp./Hum.	24 ~ 25°C /54 ~ 55%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5755MHz
		Test Voltage	DC 3.3V (Via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0





**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/09/26 ~ 10/02	Temp./Hum.	24 ~ 25°C /54 ~ 55%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	4.2dB	Frequency	TX 5795MHz
Simultaneous Factor 10 log(n)	(Note: "n" is antenna number)		
	0		

