


Report No.: FA0O1814


Appendix D. Product Photos



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4GA030 Page Number : D1 of D1
Report Issued Date : Jul. 28, 2011
Report Version : Rev. 03

FCC SAR Test Report

Report No.: FA0O1814



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4GA030

Page Number : D2 of D1 Report Issued Date: Jul. 28, 2011 Report Version : Rev. 03



Report No.: FA0O1814

Appendix E. Test Setup Photos



Right Cheek







Left Cheek

Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4GA030 Page Number : E1 of E1
Report Issued Date : Jul. 28, 2011
Report Version : Rev. 03