

Annex 2: External photographs of EUT to TEST REPORT No.: 17-1-0180901T13

According to:

FCC Regulations

Part 15.107 Part 15.109

ISED Regulations

ICES-003, Issue 6 RSS-Gen, Issue 4

for

Datalogic S.r.l.

FALCON X4 Type:E00ANM4HS0GF0A4

FCC ID: U4GFX4WB

IC: 3862E-FX4WB

PMN: FALCON X4 | HVIN: FX4 WB GUN | FVIN: Not Applicable






TABLE OF CONTENTS:

1. EXTERNAL PHOTOGRAPHS	3
1.1. Equipment Under Test (EUT)-Radiated Test Sample	3
1.2. Equipment Under Test (EUT)-Battery	7
1.3. Auxiliary Equipment (AE)	8



1. External photographs

1.1. Equipment Under Test (EUT)-Radiated Test Sample



Photograph 1:FALCON X4 -Front Side



Photograph 2: FALCON X4 -Rear Side





Photograph 3: FALCON X4 -Top Side



Photograph 4: FALCON X4 -Bottom Side





Photograph 5: FALCON X4 –Front-Top Side



Photograph 6: FALCON X4 -Right Side





Photograph 7: FALCON X4 -Left Side



Photograph~8~FALCON~X4~-Rear~Side + Battery~outside



1.2. Equipment Under Test (EUT)-Battery



Photograph 9:FALCON X4 –Battery Outer Side



Photograph 10:FALCON X4 –Battery Inner Side



1.3. Auxiliary Equipment (AE)



Photograph 11: VW-1 Handy link/USB cable



Photograph 12: VW-1 Handy link/RS232 cable





Photograph 13:Test PC



Photograph 14: Docking Station (with Spare Battery) – Top View





Photograph 15:RS232 Null Modem cable



Photograph 16: Docking Station AC/DC Adapter





Photograph 17:USB (type-B) Cable