


Appendix B. Setup Photographs

<Conducted Emission> Mode 1



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0030 Page Number : B1 of B4
Report Issued Date : Jun. 05, 2009
Report Version : Rev. 01

Report No.: FR940109B






Report No.: FR940109B



Side View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0030 Page Number : B2 of B4
Report Issued Date : Jun. 05, 2009
Report Version : Rev. 01






Report No.: FR940109B

<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0030

Page Number : B3 of B4 Report Issued Date: Jun. 05, 2009 Report Version : Rev. 01





Report No.: FR940109B



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0030 Page Number : B4 of B4
Report Issued Date : Jun. 05, 2009
Report Version : Rev. 01