


Report No.: FA940113

Appendix D. Product Photos



Battery 1_Front

Battery 1_Rear



Battery 2_Front

Battery 2_Rear

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 D1 of D3

Report Issued Date : Dec. 09, 2009 Report Version : Rev. 01



FCC SAR Test Report



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 D2 of D3

Report Issued Date : Dec. 09, 2009


Report Version : Rev. 01

Report No.: FA940113



Report No. : FA940113

Antenna Location:



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 Page Number : D3 of D3
Report Issued Date : Dec. 09, 2009
Report Version : Rev. 01



Report No.: FA940113

Appendix E. Test Setup Photos



Right Cheek_Sample A

Right Tilted_Sample A







Left Tilted_Sample A



Face of the DUT with Phantom 1.5 cm Gap_ Sample A



Bottom of the DUT with Phantom 1.5 cm Gap_ Sample A

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 Page Number : E1 of E2
Report Issued Date : Dec. 09, 2009
Report Version : Rev. 01









Report No. : FA940113

Right Cheek_Sample B

Right Tilted_Sample B



Face of the DUT with Phantom 1.5 cm Gap_ Sample B

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 Page Number : E2 of E2
Report Issued Date : Dec. 09, 2009
Report Version : Rev. 01