3. Internal Photograph of EUT


Model Name: DL-MEMOR

Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 22 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01






Page Number : 23 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01



Report No.: EP940113




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 24 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01



Report No.: EP940113




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 25 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01



Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 26 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01



Model Name: DL-MEMOR


10 200 90 90 70 60 50 40 30 20 10 100 90 80 70 60 50 40 30 20 10 100 90 80 70 60 50 40 30 20 10 100 90 80 70 60 50 40 30 20 10 100 90 80 70 60 50 40 30 20 10 100 90 80 70 80 50 40 30 20 10 100 90 80 70 80 50 40 30 20 10 100 90 80 70 80 50 40 30 20 10 100 90 80 70 80 50 40 30 20 10 100 90 80 70 80 50 40 30 20 10 100 90 80 70 80 50 40 30 20 10 100 90 80 70 80 50 40 30 20 10 100 90 80 7

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 27 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01



Report No.: EP940113




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 28 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01





Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 29 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 30 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01





Page Number : 31 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01




Report No.: EP940113




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 32 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01






Page Number : 33 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01

Report No.: EP940113




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 34 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01





Page Number : 35 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01





Page Number : 36 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01






Page Number : 37 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01



Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 38 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01

05 04 05 02 01 001 06 08 07 09 05 04



Model Name: DL-MEMOR 60

30

10 20 30

70 60

40

30

Report No.: EP940113


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 39 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01



Report No.: EP940113




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 40 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01




Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 41 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01






Page Number : 42 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01



Report No.: EP940113




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 43 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01




Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033


Page Number : 44 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01

Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 45 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01






Page Number : 46 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01



Report No.: EP940113




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 47 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01




Page Number : 48 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01

Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 49 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01

Report No.: EP940113




530880-58810-8400-1 MADE IN GERMANY

35724701 265852 8 X9


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033

Page Number : 50 of 54 Issued Date : Dec. 09, 2009 Report Version : Rev. 01



Page Number : 51 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 52 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01


Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 53 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01



Report No.: EP940113



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0033 IC: 3862E-M0033 Page Number : 54 of 54
Issued Date : Dec. 09, 2009
Report Version : Rev. 01