

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5590MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		






Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	II-2C
		Frequency	TX 5670MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3







Test Date	2017/10/02~18	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5755MHz
		Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		3	





Test Date	2017/10/02~18	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5795MHz
		Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3






### ● Antenna: Omni-S Antenna

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5180MHz
Simultaneous Factor 10 log(n)	(Note: "n" is antenna number)	Test Voltage	DC 3.3V (through jig via Notebook PC)
			0



**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303




Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5200MHz
		Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0





Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5240MHz
		Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0





Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5260MHz
		Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0






Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2A
		Frequency	TX 5300MHz
Cable Loss	1.4dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		






Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2A
		Frequency	TX 5320MHz
Cable Loss	1.4dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		





Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5500MHz
		Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0






Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2C
		Frequency	TX 5580MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		







Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2C
		Frequency	TX 5700MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		





Test Date	2017/10/02~18	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5745MHz
		Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0





Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5785MHz
		Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			0

