


## **Appendix B. Setup Photographs**

## <Conducted Emission> Mode 1



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0030 Page Number : B1 of B4
Report Issued Date : Jun. 05, 2009
Report Version : Rev. 01

Report No.: FR940109A





Report No.: FR940109A



Side View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0030 Page Number : B2 of B4
Report Issued Date : Jun. 05, 2009
Report Version : Rev. 01






## <Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0030 Page Number : B3 of B4
Report Issued Date : Jun. 05, 2009
Report Version : Rev. 01

Report No.: FR940109A





Report No.: FR940109A



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: U4G0030 Page Number : B4 of B4
Report Issued Date : Jun. 05, 2009
Report Version : Rev. 01