

1274 Anvilwood Ave., Sunnyvale, CA 94089 USA Tel.: 408.732.9162 Fax.: 408.732.9164 http://www.baclcorp.com

2009-10-06

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

RE: Request to supersede test report for FCC ID: U5TWFDS-RUA

To Whom It May Concern:

Regarding FCC ID: U5TWFDS-RUA; we are requesting to supersede the original report due to a model name change in the support equipment that was made to the Support Equipment list, Interface Ports and Cables, and Test Setup Block Diagram. On Page 9, 10, and 24 of the original report that was uploaded on 09/29/2009 the Support equipment listed as "Splitter" has been changed to "Combiner". This model name correction has also been made to the EUT Internal Photos Exhibit.

We would like to upload the corrected test report per the clients request so that we may correct this error.

Thank you very much,

Sincerely,

Jennifer Paigly, Document Control Clerk Document Control Department

Bay Area Compliance Laboratories Corp. 1274 Anvilwood Avenue Sunnyvale, CA 94089, USA

Tel: (408) 732-9162 (**Ext.3038**)

Email: document.control@baclcorp.com