
Appendix C. Set up Photograph

Spurious Radiation



FRONT VIEW

REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C1
Report Issued Date : Mar. 29, 2007
Report Version : Rev.01

Report No. : FG713005